## Climate Change and Toxic Hazards: Before, During, and After the Storm

Part II: During the Storm

Elena Craft, PhD Senior Director February 14, 2019



#### Independent Monitors Found Benzene Levels After Harvey Six Times Higher Than Guidelines

After an oil tank in Houston's Manchester neighborhood caved in, private monitors found levels that far exceeded California's health guidelines

By Lisa Song and Al Shaw, ProPublica, and Kiah Collier, The Texas Tribune, September 14, 2017



An aerial view of the Valero Houston Refinery is seen in Houston, Texas, U.S. August 31, 2017. REUTERS/Adrees Latif Published Credit: adrees latif/Reuters PHOTO: ADREES LATIF/REUTERS




After Oil Refinery Is Damaged by Harvey, Benzene Is Detected in Houston Area

City and EPA investigate potentially dangerous plume after Valero Energy Partners reported leak tied to hurricane

# High levels of chemicals found in air around Houston refinery after EPA told residents not to worry

The revelations came after an environmental group conducted its own testing.

#### Hurricane Florence Risk Sites






### Researchers respond quickly after Hurricane Florence

◆ Previous Article Next Article ▶

After Hurricane Florence devastated southeastern North Carolina, NIEHS grantees hit the ground running to test for contaminants.

BY SARA AMOLEGBE








#### Air

#### **Ambient** Benzene Concentration Coharie Sdisa ug/m<sup>3</sup> Fort Bragg 0.00 - 0.33Military Reservation 0.34 - 0.630.64 - 1.271.28 - 2.36 2.37 - 10.99 Water samples 0 omperton Limited Access Highway Waccama Major Road Siouan D Local Road Columbus Columbus Minor Road Other Road Ramp Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USCS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordinance Survey, Esri Japan, METI, esti China (Hong Kong), swisstopo, © OpenStreetMap contributors, and the GIS User Ferry Pedestrian Way

#### Water





NASA/USGS Photo



Elena Craft, PhD ecraft@edf.org

Photo: Jay Janner